

Link do produktu: <https://www.ekactus.pl/kolo-fi-205-przednie-kosiarki-murray-blokada-p-5552.html>

KOŁO FI 205 PRZEDNIE KOSIARKI MURRAY/BLOKADA

Cena brutto	190,93 zł
Cena netto	155,23 zł
Dostępność	Dostępny
Numer katalogowy	5693000083736

Opis produktu

Koło przednie kosiarki Murray

Oryginał: 071133MA

Pasuje do modeli:

228511x31A (2002), 228511x31B (2003), 228511x31C (2003), 228511x31D (2004), 228511x8E (2004), 228610x50A (2003), 228610x50B (2004), 228610x68A (2002), 228610x68B (2003), 228610x68C (2004), 228610x68D (2005), 228610x6A (2001), 228610x6B (2001), 228610x89A (2002), 228611x50A (2005), 228650x50A (2005), 228650x6A (2001), 228650x89A (2001), 228650x89B (2002), 228650x99A (2003), 228651x89A (2002), 22865x50A (2002), 22865x50B (2003), 22865x50C (2004), 22805x31A (2000), 228410x199C (2005), 228510x24A (2003), 228510x99A (2004), 228510x99B (2005), 228511x24A (2004), 228511x8A (2002), 228511x8B (2002), 228511x8C (2002), 228511x8D (2002), 228511x8D (2003), 228512x8A (2005), 228610x14A (2001), 228610x30A (2005), 228610x31A (2005), 228610x692A (2003), 228651x99A (2004), 228651x99B (2005), 22865x14B (2001), 228690x24A (2003), 228690x99A (2002), 228690x99A (2003), 229160x199A (2003), 229510x48A (2003), 229510x99A (2004), 229610x199A (2003), 229610x24A (2003), 229610x89A (2001), 229610x89C (2002), 229610x89C (2003), 229610x8A (2002), 229611x24A (2004), 229611x99A (2005), 229610x30A (2005), 228651x92A (2005), 228690x24B (2005), 22605x50C (2000), 22605x50D (2001), 22605x50E (2001), 22605x50F (2002), 22605x50G (2003), 22605x50H (2004), 22605x51B (2000), 22606B (1999), 22607x71B (1999), 226110x18A (2003), 226110x24A (2003), 226110x48A (2004), 226110x50A (2005), 226110x52A (2004), 226110x6A (2002), 226110x71A (2001), 226110x92A (2003), 226111x52A (2004), 226111x52B (2005), 226111x92A (2004), 226112x52A (2005), 226130x192A (2003), 226130x6A (2001), 226130x92A (2002), 22615x14A (2000), 22615x14B (2001), 22615x194A (2000), 22615x194B (2000), 22615x8A (2000), 22615x8B (2000), 22615x8C (2001), 22615x92A (1999), 22615x92B (2000), 22617x192A (2000), 22617x194B (2001), 22617x592A (2000), 22617x92A (2000), 22617x92B (2001), 22646x6B (1999), 22646x6E (2001), 22646x6F (2002), 22646x92A (1999), 22648x4A (2000), 22648x71B (1999), 22655x192A (2000), 22655x592A (2000), 22655x92A (2000), 227110x71A (2001), 22715x92A (1999), 22716x192A (2000), 22716x592A (2000), 22716x92A (2000), 226110x24A (2005), 226111x48A (2005), 226111x92A (2005), 20605x7A (1997), 20605x8A (1997), 20606x30A (1999), 20606x30B (2000), 20606x30C (2001), 20606x30D (2002), 20606x30E (2003), 20606x50C (1998), 20606x50D (1998), 20606x50E (1998), 20606x6C (2000), 20606x82B (2000), 20606x82C (2000), 20606x8A (1998), 20606x8B (1998), 20607A (1999), 20607x30A (1999), 20607x71A (1999), 20607x99B (1999), 20608A (2000), 20608B (2000), 20608C (2000), 20608x199A (2000), 20608x199B (2000), 20608x34B (1999), 20608x4A (1999), 20608x4B (2000), 20608x4C (2000), 20608x6A (2000), 20608x6B (2000), 20608x99A (2000), 20608x99B (2000), 20615x51A (2000), 20615x8A (1999), 20615x8B (1999), 20615x8B (2000), 20615x92A (1999), 20616x50A (2000), 20616x50B (2000), 20616x50C (2001), 20616x50D (2001), 20616x50D (2002), 20616x50F (2003), 20616x50F (2003), 20616x50G (2004), 206230x99A (2000), 206230x99B (2001), 206310x192A (2001), 206310x192A (2002), 206310x194A (2001), 206310x92A (2001), 206310x92A (2002), 206311x92A (2002), 20645x189A (2000), 20645x189B (2000), 20645x192A (2000), 20645x192B (2000), 20645x89A (2000), 20645x89B (2000), 20645x92A (2000), 20645x92B (2000), 20646x8A (1999), 20647x89A (1998), 20647x89A (1999), 20647x89B (1998), 20647x89C (2000), 20647x89D (2000), 20647x89E (2002), 206510x50A (2005), 20656x31A (1998), 20656x8A (1998), 20656x8B (1998), 20665x31A (1999), 20665x7A (2000), 20665x8A (1999), 20665x8B (1999), 20665x8B (2000), 20705x51D (1999), 20706x6B (2000), 20706x6C (2000), 20707x89A (1998), 20707x89A (1999), 20708x89A (2000), 20708x89B (2000), 20715x92A (1999), 20716x50A (2000), 20716x50C (2001), 207350x192A (2001), 20745x192A (2000), 20745x192B (2000), 20745x194C (2001), 20745x92A (2000), 20745x92B (2000), 20745x92C (2001), 207610x52A (2005), 22755x50A (1997), 22757x18A (1997), 20605x31A (1997), 20605x50A (1997), 21717x62A (1996), 21765C (1996), 21765x24A (1996), 21778x199A (1996), 21785x8D (1996), 21865x62A (1996), 21865x7A (1996), 21865x8A (1996), 206110x99A (2002), 22855x21A

(1996) , 22855x29A (1996) , 22855x6A (1996) , 22859x7A (1996) , 22859x8A (1996) ,

SZEROKOŚĆ: 45MM
ILOŚĆ ZĘBÓW: 50SZT
ŚREDNICA EWNĘTRZNA 120MM