


Link do produktu: <https://www.ekactus.pl/kolo-pasowe-murray-zamiennik-420613-91178-p-107445.html>

KOŁO PASOWE MURRAY ZAMIENNIK 420613 91178

Cena brutto	39,00 zł
Cena netto	31,71 zł
Dostępność	Aktualnie niedostępny
Numer katalogowy	2056930020173

Opis produktu

KOŁO PASOWE TRAKTORA KOSIARKI MURRAY ZAMIENNIK 420613 91178 RO7127 20613

Szerokość paska: 13mm

Pasuje do modeli:

30500x92A (1998), 30500x92A (1999), 30504x92A (1999), 30540x20E (1996), 30540x20F (1997), 30540x20G (1998), 30540x29A (1997), 30540x29B (1998), 30540x29D (1999), 30540x66F (1997), 30540x67A (1996), 30540x67C (1997), 30540x67D (1998), 30540x67F (1999), 30540x98A (1998), 30540x98B (1999), 30544x192A (1996), 30544x92D (1996), 30545x192A (1997), 30545x92A (1997), 30545x92B (1999), 30546x199A (1997), 30546x4A (1997), 30546x99A (1998), 30550E (1996), 30550F (1997), 30550G (1998), 30550H (1998), 30550H (1999), 30550x199A (1996), 30550x30A (1998), 30560D (1996), 30560E (1997), 30560F (1998), 30560x20E (1996), 30560x50A (1997), 30560x50B (1998), 30560x50C (1999), 30560x51A (1997), 30560x51B (1998), 30560x51C (1999), 30560x59A (1997), 30560x5D (1996), 30560x66B (1996), 30560x70D (1996), 30565A (1997), 30565B (1998), 30575x31A (1997), 30575x7A (1996), 30575x8A (1996), 30576x10B (1998), 30576x10B (1997), 30576x10D (1999), 30577x31A (1998), 30577x7A (1997), 30577x8A (1998), 40560x50A (1998), 40560x50B (1998), 40561x51A (1998), 40563x86A (1998), 40563x88A (1998), 40564x51A (1998), 40566x95A (1999), 40900x20C (1996), 40900x20D (1996), 40901x70C (1996), 40901x70D (1996), 40907x20B (1996), 40907x20C (1996), 40908x70B (1996), 40908x70C (1996), 42560x192A (1997), 42560x192B (1997), 42560x30A (1998), 42560x83A (1997), 42560x92A (1997), 42560x92B (1997), 42561x8A (1997), 42561x8B (1997), 42564x50A (1997), 42564x59A (1997), 42567x30A (1998), 42567x6A (1997), 42568x50A (1997), 42568x59A (1997), 42570x18A (1997), 42578x30A (1998), 42578x6A (1997), 42581x95A (1997), 42583A (1998), 42583x82A (1998), 42583x9A (1998), 42586x8A (1998), 42586x9A (1998), 42588x29A (1998), 42588x52A (1998), 42589x8 (1999), 42590A (1998), 42590x92A (1998), 42590x92B (1999), 42591x86A (1998), 42591x92A (1998), 42591x92A (1999), 42597x95A (1999), 42910A (1996), 42910Ax92A (1996), 42910x192A (1996), 42910x192B (1996), 42910x192C (1996), 42910x30A (1996), 42910x92A (1996), 42910x92B (1996), 42910x92C (1996), 42911x65B (1996), 42911x65C (1996), 42912x70B (1996), 42912x70C (1996), 42913x5B (1996), 42915x30B (1997), 42915x62A (1996), 42915x6A (1996), 42916x7B (1996), 42916x8A (1996), 42916x8B (1996), 42917x6A (1996), 42917x6B (1996), 42917x6C (1996), 42917x8A (1996), 42917x8B (1996), 42918x8A (1996), 42918x8B (1996), 46102x6A (1999), 46103A (1999), 46103x71A (1999), 46103x92A (1999), 46104x8A (1999), 46250x30A (1996), 46250x65C (1996), 46254x15B (1996), 46258x6A (1996), 46400A (1996), 46400x50A (1997), 46400x5A (1996), 46400x65A (1996), 46401x30A (1998), 46401x6A (1996), 46403x199A (1996), 46403x30A (1996), 46403x8A (1996), 46404x21A (1996), 46404x6A (1996), 46404x89A (1997), 46404x8A (1996), 46560x192A (1997), 46560x92A (1997), 46562x8A (1997), 46562x8B (1997), 46567x30A (1998), 46567x6A (1997), 46567x6B (1997), 46568A (1997), 46568x6A (1998), 46569x6A (1998), 46569x71A (1998), 46569x92A (1998), 46569x9A (1998), 46570x6A (1998), 46570x71A (1998), 46570x8A (1998), 46573x92A (1998), 46576x92A (1999), 46900B (1996), 46901x192A (1996), 46901x92B (1996), 46904x192A (1996), 46904x92A (1996), 46905x30A (1996), 46906x199A (1996), 46906x99A (1996), 46907A (1996), 48560x192A (1997), 48560x92A (1997), 50568x9A (1998), 52100x92A (1999), 52161x89A (1999), 52461x89A (1998)