

Link do produktu: <https://www.ekaktus.pl/pasek-klinowy-napedu-nozy-murray-037x88ma-p-1117.html>

PASEK KLINOWY NAPĘDU NOŻY MURRAY 037X88MA

Cena brutto	218,53 zł
Cena netto	177,67 zł
Dostępność	Dostępny
Numer katalogowy	5693000040692

Opis produktu

Pasek napędu noży traktorka kosiarki Murray

Oryginał: 037X88MA

Pasuje do modeli:

42531x7A (1997), 42531x8A (1997), 42561x8A (1997), 42561x8B (1997), 425000x8A (2003), 425000x8B (2004), 425001x31A (2004), 425001x8A (2004), 425001x8B (2004), 425001x8C (2005), 425001x8D (2005), 425001x8E (2005), 425001x99A (2005), 425002x99A (2003), 425003x31A (2001), 425003x71A (2001), 425003x8A (2000), 425004x99A (2004), 425004x99B (2004), 425005x8A (2004), 425005x8B (2004), 425007x92A (2002), 425007x92B (2003), 425007x92C (2003), 425008x31A (2002), 425008x8A (2002), 425009x31A (2002), 425009x8A (2002), 42500A (1998), 42500B (1999), 42500C (2000), 42500D (2001), 42500x30A (1998), 42500x30B (1999), 42500x82A (1998), 42500x82B (1999), 42500x99A (2000), 425012x31A (2005), 425013x92A (2003), 425014x92A (2004), 425014x92B (2005), 425014x92C (2005), 425015x92A (2004), 425015x92B (2004), 425016x48A (2005), 425016x78A (2004), 425017x190A - 552548 (2006), 425017x24A (2005), 425017x78A (2005), 425018x00A (2007), 42504x71A (1998), 42504x71B (1999), 42504x99A (1998), 42504x99B (1999), 42505x92A (1998), 42506x92A (1998), 42508x92A (1999), 42509x92B (1999), 42510A (1999), 42511x4A (1999), 42511x4B (2000), 42512x99A (1999), 42514x31A (2000), 42514x8A (2000), 42515x92A (2000), 42515x92B (2001), 42515x92B (2002), 42516x92A (2000), 42516x92B (2001), 42516x92B (2002), 42517x82A (2000), 425303x92A (2002), 425303x92B (2003), 425306x48A (2003), 425307x24A (2003), 425308x31A (2005), 42534x30A (1998), 42537A (1998), 42539A (1998), 42544x31A (1998), 42544x8A (1998), 42544x8B (1998), 42544x8C (1999), 42544x8D (1999), 42544x8E (1999), 42544x8F (2000), 42544x8G (2001), 42544x99A (1999), 42545x29A (1998), 42545x29B (1999), 425600x31A (2003), 425600x48A (2005), 425600x8A (2003), 425601x53B (2001), 425602x50A (2002), 425603x99A (2003), 425604x18A (2003), 425604x18B (2004), 425604x99A (2004), 425604x99C (2005), 425607x52A (2005), 42560x30A (1998), 42560x52A (2000), 425610x99A (2001), 425610x99B (2001), 425611x99A (2001), 425611x99B (2001), 425611x99C (2002), 425612x99A (2002), 425613x31A (2002), 425613x8A (2002), 425614A (2002), 425614x92A (2002), 425615x30A (2003), 425615x50A (2003), 425615x50B (2004), 425615x52A (2004), 425615x78A (2004), 425615x99B (2005), 425618x48A (2003), 425619x24A (2003), 425619x24B (2004), 425620x92A (2004), 425621x108A (2005), 425621x53A (2004), 425622x50A (2005), 425622x50B-SW (2006), 425622x50C (2007), 425622x78A (2005), 425622x78B (2006), 425624x18A (2005), 425624x190A - 552547 (2006), 425638x692A (2003), 425640x50A (2005), 425640x50B-SW (2006), 42564x50A (1997), 42567x30A (1998), 42569x4A (2000), 42569x6A (2000), 42571x14A (2000), 42571x14B (2001), 42571x31A (2000), 42571x31B (2001), 42571x8A (2000), 42571x8B (2001), 42571x8C (2001), 42571x8D (2001), 42572x31A (2000), 42572x8A (2000), 42575x81A (2000), 42575x81B (2001), 42576x92A (2000), 42576x92B (2000), 42576x92C (2001), 42576x92D (2001), 42578x30A (1998), 42583A (1998), 42583B (1999), 42583C (1999), 42583x30A (1999), 42583x30B (1999), 42583x6A (2000), 42583x6B (2001), 42583x6C (2002), 42583x82A (1998), 42583x82C (1999), 42583x9A (1998), 42586x8A (1998), 42586x9A (1998), 42588x29A (1998), 42588x52A (1998), 42588x52B (1999), 42588x70A (1999), 42590A (1998), 42590B (1999), 42590C (2000), 42590E (2002), 42590x92A (1998), 42590x92B (1999), 42591x31A (1999), 42591x86A (1998), 42591x86B (1999), 42591x86C (2000), 42591x88A (1999), 42591x88A (2000), 42591x88B - (VRO4216HX) (1999), 42591x8A (1999), 42591x8B (1999), 42591x92A (1998), 42591x92A (1999), 42597x95A (1999), 42598x92A (1999), 42598x92A (2002), 7800282 - 425307x51A (2008), 7800298 - 405606x108D (2009), 7800302 - 425017x78B (2008), 7800303 - 425621x108C/D (2008), 7800304 - 425622x78C (2008), 7800361 - LT135420C (2008), 7800362 - LT155420C (2008), 7800370 - FLT185420 (2008), 7800562 - MT175420 (2009), 7800563 - MT195420 (2009), 7800566 - RT155420, 15.5HP 42" (2009), 7800581 - MT155420, 15.5HP 42" (2009), 2690892 - EBL155420H, 15.5HP 42" (2010), 7800480 - ELT155420GF, 15.5HP 42" (2009), 7800481 - ELT155420HF, 15.5HP 42" (2009), 7800485 - EYK155420GF, 15.5HP 42" (2009), 7800486 - EYK155420HF, 15.5HP

42" (2009) , 7800497 - EBL155420H, 15.5HP 42" (2009) , 7800162 - LT155420, 15.5HP 42" (2008) , 7800191 - LT185420, 18.5HP 42" (2008) , 7800307 - CLT155420, 15.5HP 42" (2008) , 7800309 - CLT185420, 18.5HP 42" (2008) , 7800162E - ELT155420, 15.5HP 42" (2010) , 7800307E - ELT155420, 15.5HP 42" (2010) , 7800410 - ELT155420G, 15.5HP 42" (2009) , 7800411 - ELT155420H, 15.5HP 42" (2009) , 7800413 - EYK155420G, 15.5HP 42" (2009) , 7800414 - EYK155420H, 15.5HP 42" (2009)