

Link do produktu: <https://www.ekaktus.pl/wal-korbowy-silnika-briggs-600-n-typ-22-50-594572-p-98143.html>



WAŁ KORBOWY SILNIKA BRIGGS 600 N TYP 22/50 594572

Cena brutto	317,62 zł
Cena netto	258,23 zł
Dostępność	Dostępny
Czas wysyłki	24 godziny
Numer katalogowy	5693000152586
Kod producenta	594572
Kod EAN	5693000152586
Producent	Brak

Opis produktu

WAŁ KORBOWY SILNIKA KOSIARKI BRIGGS 600 NOWY TYP 22/50

Numer części: 594572

A = 22 mm
B = 27 mm
C = 25,4 mm
D = 16 mm

Pasuje do modeli:

103M02, 103M0B, 104M02, 104M05, 104M0B

103M02-0009-H1, 103M02-0009-H5, 103M02-0014-H1, 103M02-0014-H5, 103M02-0019-H1, 103M02-0021-H1, 103M02-0028-F1, 103M02-0032-H1, 103M02-0032-H5, 103M02-0036-F1, 103M02-0046-H1, 103M02-0046-H5, 103M02-0050-H1, 103M02-0053-H1, 103M02-0053-H5, 103M02-0055-H1, 103M02-0057-H1, 103M02-0060-H1, 103M02-0061-H1, 103M02-0063-H1, 103M02-0071-H1, 103M02-0082-H1, 103M02-0082-H5, 103M02-0084-H1, 103M02-0085-H1, 103M02-0086-H1, 103M02-0086-H5, 103M02-0091-H1, 103M02-0091-H5, 103M02-0092-H1, 103M02-0092-H5, 103M02-0093-H1, 103M02-0093-H5, 103M02-0099-H5, 103M0B-0051-H1, 104M02-0014-H1, 104M02-0016-H1, 104M02-0029-H1, 104M02-0030-H1, 104M02-0031-H1, 104M02-0033-H1, 104M02-0035-H1, 104M02-0035-H5, 104M02-0045-H1, 104M02-0049-H1, 104M02-0055-H1, 104M02-0055-H5, 104M02-0094-H1, 104M02-0112-H1, 104M02-0122-H1, 104M02-0124-H1, 104M02-0127-H1, 104M02-0127-H5, 104M02-0135-H1, 104M02-0137-H1, 104M02-0149-H1, 104M02-0149-H5, 104M02-0161-H1, 104M02-0161-H5, 104M02-0165-H1, 104M02-0169-H1, 104M02-0169-H5, 104M02-0173-H1, 104M02-0184-H1, 104M02-0184-H5, 104M02-0188-H1, 104M02-0192-H1, 104M02-0195-H1, 104M02-0200-H1, 104M02-0200-H5, 104M02-0209-H1, 104M02-0209-H5, 104M02-0212-H1, 104M02-0214-H1, 104M02-0216-H1, 104M02-0216-H5, 104M02-0219-H1, 104M02-0219-H5, 104M02-0225-H5, 104M05-0024-H1, 104M05-0032-H1, 104M05-0032-H5, 104M05-0037-H1, 104M05-0047-H1, 104M05-0047-H5, 104M05-0050-H1, 104M05-0050-H5, 104M05-0063-H1, 104M05-0064-H1, 104M0B-0075-H1, 104M0B-0076-H1, 104M0B-0079-H1, 104M0B-0121-H1, 104M0B-0123-H1, 104M0B-0123-H5, 104M0B-0143-H1, 104M0B-0143-H5, 104M0B-0144-H1, 104M0B-0171-H1, 104M0B-0171-H5, 104M0B-0172-H1, 104M0B-0172-H5, 104M0B-0178-H1, 104M0B-0199-H1, 104M0B-0213-H1, 104M0B-0217-H1, 104M0B-0217-H5, 104M0B-0218-H1, 104M0B-0218-H5